

KINZE SERIES 2500/3500 TWINLINE PLANTER

6 Row Narrow and 8 Row Narrow

Model No.'s to order for each planter configuration

| | | Quantity to order for each planter | |
|---|---|------------------------------------|---------|
| | | 6 R N | 8 R N |
| LIQUID FERTILIZER COULTER | 2995-017 <i>order 2990-154 & 3010-303 and choice of blade</i> | 6 | 8 |
| FRAME MOUNTED | 2995-065-L/R <i>order 2990-154 & 3010-303 and choice of blade</i> | 3 and 3 | 4 and 4 |
| | 2995-056 (pusher fert coulters kit) | 2 | 2 |
| Unit Mounted Liquid Fertilizer Coulters | 2959-003 (2" offset fert. injection) | 6 | 8 |
| | w/ 2967-180A (Residue manager for 2959-003) | Optional | |
| | 2975-188 (set back bracket) | Required | 4 |
| | or 2962-003A and 2962-004A RUMDDFO | | |
| | w/ 2962-005 (Residue Manager for 2962-003/-004) | Optional | |
| | or 2968-021A-R-LB/-L-LB Row Unit mount | | |
| | & 2968-132 10" wheel or 2968-133 11" wheel assembly | | |
| 2960 UNIT MOUNTED CONSERVATION COULTERS ONLY | 2960-033 Coulters w/ U.N.T. bracket (Kinze)** | | |
| | or 2960-127 (unit coulters only)** | 6 | 8 |
| CLEAN UP CREW ONLY | 2940-001 Pneumatic assembly | | |
| | or 2967-013A Short / Narrow UNT | | |
| | or 2967-028 Universal unit mounted residue manager | | |
| | or 2967-029A Short UNT | | |
| | or 2967-048 Narrow row unit mounted Residue Manager | 6 | 8 |
| | or 2967-052 Screw Adjust (1993 to current) | | |
| | or 2967-054 Narrow row Screw Adjust (1993 to current) | | |
| | or 2967-056 Narrow row Screw Adjust (pre- 1993) | | |
| | or 2967-057 Screw Adjust (pre- 1993) | | |
| | 2975-188 (set back)*** | Required | 4 |
| Combination Attachments | 2967-006 Floating Residue Manager fits Kinze Unit Mount Coulters | | |
| | or 2967-007 U.N.T. (use with 2960-033 coulters) | | |
| | or 2967-035 Titan Universal | 6 | 8 |
| | or 2967-115 (for use with 2960-127 coulters) | | |
| | 2967-070 (Quick adjust) | Optional | |

** See the price book for blade choices.

*** Must be used on center 4 rows when using -115 or -035 Clean Up Crew

NOTE - 2960 UNIT MOUNTED COULTERS AND THE CLEAN UP CREW CANNOT BE USED TOGETHER - EXCEPT FOR 2967-115.
NOTE - DUE TO MANUFACTURING CHANGES IN PLANTER, SOME ATTACHMENTS MAY NOT BE USED OR MODIFIED.